

Brand/Model	Year	Shock part No.	Type Code	Price	Length	Stroke	Spring	Fork spring Part No.	Price
Honda									
Ape 50/100		HO 513	S36E	£ 327.43	261	38	00281-38		
Ape 50/100		HO 511	S36HR1C1L	£ 599.33	263 +2,5/-2,5	38	00281-39		
CB 400 Superfour	1992-93	HO 142*	S36P	£ 573.52	330	88	00480-02		
CB 400 Superfour	1992-93	HO 145*	S36PR1C1LB	£ 1,015.43	325 +10/-0	92	00380-04		
CB 600F Hornet	1998-02	HO 803	S46HR1C1	£ 633.62	303	53	01093-64	08803-01/ -03	£ 98.19
CB 600F Hornet	2003-04	HO 541	S46HR1C1L	£ 667.62	304 +11,5/-0,5	53,5	01093-64	08803-02/ -04	£ 98.19
CB 600F Hornet	2003-04	HO 803	S46HR1C1	£ 633.62	303	53	01093-64	08803-02/ -04	£ 98.19
CB 600F Hornet	2007-08	HO 707	S46HR1C1	£ 633.62	307,5	50,5	01093-64	08747-90	£ 98.19
CB 750 F	1980-84	HO 140*	S36P	£ 573.52	364	97	00480-03		
CB 750 F	1980-84	HO 153E*	S36E	£ 430.48	365	98	00380-05		
CB 750 KZ	1979-84	HO 140*	S36P	£ 573.52	364	97	00480-03		
CB 750 KZ	1979-84	HO 153E*	S36E	£ 430.48	364	97	00480-03		
CB 750 Seventy	1992-94	HO 141*	S36P	£ 573.52	356,5	98	00480-02		
CB 900	1979-84	HO 140*	S36P	£ 573.52	364	97	00480-03		
CB 900	1979-84	HO 146*	S36PR1C1LB	£ 1,015.43	358 +10/-0	92	00380-05		
CB 900	1979-84	HO 153E*	S36E	£ 430.48	365	98	00480-03		
CB 900F Hornet	2002-03	HO 201	S46HR1C1S	£ 821.90	283	50,5	01093-74	08686-85	£ 98.19
CB 900F Hornet	2004-06	HO 201	S46HR1C1S	£ 821.90	283	50,5	01093-74		
CB 1000 BIG	1993-97	HO 143*	S36P	£ 573.52	356,5	92	00480-03	08833-01	£ 98.19
CB 1000 BIG	1993-97	HO 144*	S36PR1C1LB	£ 1,015.43	358 +10/-0	92	00480-13	08833-01	£ 98.19
CB 1000 R	2008	HO 808	S46HR1C1S	£ 821.90	309,5	47,5	01093-64	08665-90/ -95	£ 98.19
CB 1000 R	2008-09	HO 009	S46DR1	£ 430.48	310	56	01095-64		
CB 1100	2010	HO 010*	S36DR1L	£ 720.10	362 +5/-5	83	00480-03 (B)		
CB 1100	2010	HO 011*	S36DR1L	£ 720.10	362 +5/-5	83	21211-03 (C)		
CB 1100 F	1982-85	HO 140*	S36P	£ 573.52	364	97	00480-03		
CB 1100 F	1982-85	HO 153E*	S36E	£ 430.48	365	98	00380-05		
CB 1100 R	1981-84	HO 140*	S36P	£ 573.52	364	97	00480-03		
CB 1100 R	1981-84	HO 153E*	S36E	£ 430.48	365	98	00380-05		
CB 1300	1999-01	HO 147*	S36PR1C1LB	£ 1,015.43	310 +10/-0	71	00180-57		
CB 1300	2003-09	HO 150*	S36PR1C1LB	£ 1,015.43	365 +8/-2	94	00480-13		
CB 1300	2003-09	HO 414*	S36PR1C1L	£ 1,015.43	365 +8/-2	92	00480-23 (B)		
CB 1300	2003-09	HO 417*	S36PR1C1L	£ 1,015.43	365 +8/-2	92	00480-33 (Y)		
CBF 600 SA	2008	HO 809	S46DR1S	£ 633.62	310	45,5	01092-84		
CBF 1000	2006-09	HO 603	S46HR1C1S	£ 821.90	293,5	56,5	01093-69	08757-85	£ 98.19
CBF 1000	2006-09	HO 044	S46DR1	£ 430.48	293,5	51,5	01093-69	08757-85	£ 98.19
CBF 1000 F	2010	HO 015	S46HR1C1S	£ 821.90	311,5	44,5	01092-91		
CBR 600 RR	2003-04	HO 301	S46PR1C2LS	£ 1,015.43	313,5 +0/-6	59,5	01093-31	08694-90/ -95/ -10	£ 98.19
CBR 600 RR	2005-06	HO 502	S46PR1C2LS	£ 1,015.43	310,5 +3/-3	59,5	01093-31	08715-90/ -95/ -10	£ 98.19
CBR 600 RR, not ABS	2007-10	HO 789	T36PR1C1LS	£ 1,015.43	295 +6/-0	60	21040-31	08747-90/ -95/ -10	£ 98.19
CBR 600 RR, with ABS	2009-10	HO 889	T36HR1C1LS	£ 1,015.43	295 +6/-0	60	21040-31	08747-90/ -95/ -10	£ 98.19
CBR 900 RR	1998-99	HO 802	S46HR1C1L	£ 667.62	303 +12/-0	57	01093-59	08635-90	£ 98.19
CBR 900 RR / 929	2000-01	HO 152	S46PR1C2LS	£ 1,015.43	286 +4/-2	57	01093-59	08664-95	£ 98.19
CBR 900 RR / 954	2002-03	HO 202	S46PR1C2LS	£ 1,015.43	288 +2/-4	57	01093-59	08665-85/ -90/ -95	£ 98.19
CBR 1000 RR	2004-05	HO 347	S46PR1C2LS	£ 1,015.43	314 +6/-0	58	01093-39	08704-95/ -10	£ 98.19
CBR 1000 RR	2006-07	HO 604	S46PR1C2LS	£ 1,015.43	314 +6/-0	58	01093-44	08704-95/ -10	£ 98.19
CBR 1000 RR	2008-10	HO 888	T36PR1C1LS	£ 1,015.43	302 +4/-2	60	21040-36	08672-95/ -10	£ 98.19
CBR 1100 XX	1997-00	HO 639	S46HR1C1S	£ 821.90	319	52	01092-69	08633-95	£ 98.19
CBR 1100 XX	2001-06	HO 518	S46HR1C1S	£ 821.90	319	52	01092-69	08633-95	£ 98.19
CBX 1000	1978-81	HO 140*	S36P	£ 573.52	364	97	00480-03		
CBX 1000	1978-81	HO 153E*	S36E	£ 430.48	365	98	00480-03		
Foresight FEZ 250	1998-00	HO 839	S36E	£ 327.43	400	125	00480-11		
Moriwaki MD 250H/ S	2009	MH 841	T36PR1C1L	£ 942.38	310 +4/-2	55	21041-24		
NSR Mini		HO 418	S36HR1C1L	£ 599.33	217 +9/-1	34	00282-04		
NSR Mini		HO 890	T36PR1C1L	£ 888.48	218 +4/-2	35	21140-71		
NSR 250 R-SE	1990-93	HO 206	S46HR1C1L	£ 667.62	302 +6/-6	50	01093-49		
NSR 250 R-SP	1994-	HO 206	S46HR1C1L	£ 667.62	302 +6/-6	50	01093-49		
RS 125	1998-08	HO 406	S46PR1C1L	£ 667.62	305 +7/-5	54	01093-21		
VFR 800 FI	2002-05	HO 203	S46DR1S	£ 633.62	317,5	53,5	01092-69	08687-85	£ 98.19
VFR 800 FI	2002-05	HO 605	S46HR1C1LS	£ 856.00	317,5 +6/-0	54,5	01092-69	08687-85	£ 98.19
VFR 800 FI	2002-05	HO 043	S46DR1	£ 430.48	317,5	53,5	01092-69	08687-85	£ 98.19
VFR 800 FI	2006-09	HO 203	S46DR1S	£ 633.62	317,5	53,5	01092-69		
VFR 800 FI	2006-09	HO 605	S46HR1C1LS	£ 856.00	317,5 +6/-0	54,5	01092-69		
VFR 800 FI	2006-09	HO 043	S46DR1	£ 430.48	317,5	53,5	01092-69		
VFR 1200 F	2010	HO 013	S46HR1C1S	£ 821.90	321,5	50,5	01092-74	08795-10/ -11	£ 98.19
VTR 250	2009	HO 944	S36D	£ 277.71	295	48	00281-36		
VTR 1000 F	1997-06	HO 701	S46HR1C1S	£ 821.90	346	60	01092-64	08805-01	£ 98.19
VTR 1000 SP2 / RC 51	2000-01	HO 204	S46PR1C2LS	£ 1,015.43	326 +10/-2	63	01092-29	08662-10	£ 98.19
VTR 1000 SP2 / RC 51	2002-06	HO 204	S46PR1C2LS	£ 1,015.43	326 +10/-2	63	01092-29	08662-10	£ 98.19
XL 700 V Transalp	2008	HO 823	S46ER1S	£ 633.62	316,5	65,5	01092-59		
XL 1000 V Varadero	1999-02	HO 851	S46HR1C1S	£ 821.90	338	65	01095-54	08655-70	£ 98.19
XL 1000 V Varadero	1999-02	HO 046	S46DR1	£ 430.48	338	65	01095-54	08655-70	£ 98.19
XL 1000 V Varadero	2003-09	HO 533	S46HR1C1S	£ 821.90	334	55	01095-69		
XL 1000 V Varadero	2003-09	HO 045	S46DR1	£ 430.48	334	55	01095-69		
XL 1000 V Varadero with ABS	2003-09	HO 533	S46HR1C1S	£ 821.90	334	55	01095-69	08725-85	£ 98.19
XL 1000 V Varadero with ABS	2003-09	HO 045	S46DR1	£ 430.48	334	55	01095-69	08725-85	£ 98.19
XRV 750, Africa Twin	1995-02	HO 645	S46HR1C1S	£ 821.90	380	90	01096-26		

Brand/Model	Year	Shock part No.	Type Code	Price	Length	Stroke	Spring	Fork spring Part No.	Price
-------------	------	----------------	-----------	-------	--------	--------	--------	----------------------	-------

* These shocks are delivered as pairs.